

UNITED STATES ENVIRONMENTAL PROTECTION AGE

SDMS Document ID

999 18th STREET - SUITE 300 DENVER, CO 80202-2466 http://www.epa.gov/region08

January 26, 2006

Mr./Ms. Alejandro Gardea 4726 High Street Denver, CO 80216

Dear Mr./Ms. Alejandro Gardea,

This letter certifies that soils on the property at 4726 High Street in Denver, Colorado, have been remediated in accordance with the U.S. Environmental Protection Agency's (EPA) Record of Decision for the Vasquez Boulevard and Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, signed by EPA on September 25, 2003. The required work was accomplished in accordance with EPA approved work plans. The remediation successfully addressed the health risks associated with exposure to arsenic and lead in soils at this property.

The clean-up action conducted by the EPA and the U.S. Army Corps of Engineers (USACE) addressed residences where the soil concentrations of lead and/or arsenic exceeded the action levels of 400 parts per million (ppm) and/or 70 ppm, respectively. The clean up consisted of excavation of the top 12 inches of soil at the listed property. The excavated area was replaced with clean soils.

In order to assure that your property remains protected from lead contamination, it may be necessary to maintain the exterior of your home to prevent any chipping or peeling paint from being deposited in your yard. Very old paint (from 1978 or before) could contain lead contaminates. An EPA representative will be contacting you to schedule a lead based paint assessment of the exterior of your home. EPA will provide for the initial abatement of lead based paint if necessary.

If you require more specific information concerning the clean-up of your property, please contact me at U.S. EPA (8EPR-SR), 999 18th Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sincerely,

Victor Ketellapper

Project Manager



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8
999 18th STREET - SUITE 300
DENVER, CO 80202-2466
http://www.epa.gov/region08

26 de Enero de 2006

Señor /Señora Alejandro Gardea 4726 High Street Denver, CO 80216

Estimado(a) Señor/Señora Alejandro Gardea,

Este carta certifica que tierra en el propiedad 4726 High Street en Denver Colorado, ha sido remediado de acuerdo con la U.S. Environmental Protection Agency's (EPA) Recuerdo de Decisión para el Vasquez Boulevard y Interstate 70 Superfund Site (VB/I-70), Operable Unit 1, Firmado por EPA en September 25, 2003. El trabajo requerido era realizado de acuerdo con EPA confirmado plan del trabajo. La remediación eliminado con éxito los riesgos asociados con la exposición a arsénico y plomo en la tierra en su propiedad.

La acción de limpieza conductazo por EPA y el U.S. Army Corps of Engineers (USACE) dirigido a residentes donde las concentraciones de plomo y/o arsénico en la tierra excedido el nivel de acción de 400 partes por millón (ppm) y/o 70 ppm respectivamente. La limpieza consistido de la excavación de la primera doce pulgadas de tierra de la propiedad listado. El área excavado era reemplazado con tierras limpias.

Para asegurar que su propiedad permanece protegido de la contaminación de plomo, podría ser necesario a mantener el exterior de su hogar a prevenir cualquier astilla o la pintura a se descascara y deposita en su propiedad. Pintura muy viejo (de 1978 o antes) podría contener contaminantes de plomo. Un representante de EPA les contactará a hacer una reunión para una evaluación de pintura con plomo para la exterior de su hogar. EPA provendrá la primera rebaja de pintura basado con plomo si sea necesario.

Si quisiera mas información especifica en relación de la limpieza de su propiedad, por favor contáctame en U.S. EPA (8EPR-SR), 999 18th Street, Suite 300, Denver, CO 80202-2466, Attn: Victor Ketellapper, or 303-312-6578, or Pat Courtney at 303-312-6631.

Sinceramente,

Victor Ketellapper Gerente del Proyecto

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Site Coordination Office at (303) 487-0377.

I grant access to my properties	I do not grant acc	cess to my properties
Signature 303.308.1387	Signature	Date
☐ I would like to be present during any sampl ☐ My property has a working sprinkler system	_	d.
Page 2 o	of 2	

- Remover obstrucciones, incluyendo botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la / EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame a la officina de VB/I-70 a (303) 487-0377.

Si, yo permito acceso	a mi propiedad.	No permito acceso a	mi propiedad.
2/9/05			
Firma /	Fecha	Firma/	Fecha
		ier colección de muestras. ntas y sacate (sprinkler system).	
	Página 2	of 2	







VB/I-70 Site Coordination 10 E. 55th Avenue **Denver, CO 80216**



PROPERTY INFO	MATION		DECISION CRITE	
Property ID:	3569		Target Property?	Yes
House Number:	4726		Soil Sampled?	Yes
Street:	HIGH ST		Removal Required?	Yes
Address:	4726 HIGH ST	Find Record	Removal Complete?	
Unit:				
ZIP Code:	80216	1	SOIL SAMPLE R	ESULTS
Neighborhood:	ELYRIA	a	Phase 3B	
Zone:	R2		•	·
Zone.	ļr.z		Arsenic Decision Valu	Total Residence
OWNER INFORMA	1		Arsenic Decision Value Lead Decision Value	e 4
	1	Proprieta de la companya della companya della companya de la companya de la companya della compa		Total Residence
OWNER INFORMA	TION			Total Residence
OWNER INFORMA	ATION CONSERVATIVE CAPITAL			
OWNER INFORMA Owner Name: Mailing Address:	CONSERVATIVE CAPITAL 4875 E 117TH DR		Lead Decision Value	
OWNER INFORMA Owner Name: Mailing Address:	CONSERVATIVE CAPITAL 4875 E 117TH DR		Lead Decision Value OTHER SAMPLE	

•



O Real Property Search

If you have a question about the value, ownership, or characteristics of this property, or any other property in Denver, please call the Assessor at 720-913-4162.

View Map/Historic District Listing for this Property
Link to property tax information for this property
Link to sale information for this property
Link to property sales information for this neighborhood
Link to property sales information for all Denver neighborhoods

PROPERTY INFORMATION

Property Type: Residential Parcel: 0223105012000

Name and Address Information Legal Description

GARDEA,ISIDRO ALEJANDRO L 19 EXC REAR 5FT TO CITY

4726 HIGH ST
DENVER, CO 80216

BLK 5 ELYRIA
RESIDENTIAL

Property Address: Tax District

4726 HIGH ST DENV

Assessment Information

Actual Assessed Event

	Actual	Assesseu	Exempt	Taxable
Current Year				
Land	10400	830		
Improvements	99800	7940		
Total	110200	8770	0	8770
Prior Year				
Land	10400	830		
Improvements	99800	7940		
Total	110200	8770	0	8770

Style: 1 1/2 Story Reception No.: 0000238200

Year Built: 1900 Recording Date: 12/13/02
Building Sqr. Foot: 935 Document Type: Warranty

Bedrooms: 2 Sale Price: 125500

Baths Full/Half: 1/0 Mill Levy: 64.162

Basement/Finished: 0/0
Lot Size: 2,850

Tavable

Zoning: R2



August 10, 2006


Memorandum For the Record

Subject: Final Inspection/Acceptance 4726 High St

- 1) Repeated attempts to contact homeowner have been unsuccessful.
- 2) The property has been inspected jointly, by the Site Co-Ordination team, the US Army Corps of Engineers Site Manager, and the contractors Site Superintendent. It has been determined, The property has been restored In accordance with the original Restoration Agreement.
- 3) No further action is deemed necessary.
- 4) This memorandum will serve as the Final Acceptance for the subject property.

This is the guesthat laid his own sodower Thanksgiving '05 pwe can't get ahold of him through notes or calls.

Gregory P. Hoover
US Army Corps of Engineers
Site Manager



Meagan Redfern

From:

OCARS_Pro@uncc.org

Sent:

Tuesday, November 15, 2005 9:02 AM

To:

Meagan Redfern

Subject:

UNCC EMLCFM 2005/11/15 #00012 B0210916-00B NORM NEW

Type: OTHR

EMLCFM 00012 UNCCb 11/15/05 09:01 AM B0210916-00B NORM NEW STRT LREQ

Ticket Nbr: B0210916-00B

Original Call Date: 11/15/05 Time: 09:01 AM Op: MRE

Locate By Date : 11/17/05 Time: 11:59 PM Meet: N Extended job: N

State: CO County: DENVER City: DENVER

Addr: 4726 Street: HIGH ST

Grids: 03S068W14SE : 03S068W23NE : Legal: Y

Lat/Long: 39.784405/-104.965427 39.784405/-104.963635

: 39.781289/-104.965427 39.781289/-104.963635

Type of Work: SOIL EXCAVATION Exp.: N

Boring: N

Location: LOC ENTIRE LOT*ACCESS OPEN*INDIVDUAL STRUCTURE*TO INCLUDE ALL

: EASEMENTS TO CITY PROPERTY

Company : PROJECT RESOURCES INC.

Caller: MEAGAN REDFERN Phone: (303)487-0377
Alt Cont: AMY JAMES Phone: (303)487-0377

Fax: Email: MREDFERN@PROJECTRESOURCESINC.COM

Done for: CORPS OF ENGINEERS/EPA

Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA ATCT01 = AT&T

Members CMSND00= COMCAST - NORTH DENVER PCNDU0 = XCEL ENERGY-NORTH

DENVER

Members PSND14 = XCEL ENGY--APPT SCHEDULE QLNCND0= QWEST LOCAL

NETWORK

Members QLNCND1= QWEST LOCAL NETWORK QWSTEN0= QWEST/ENRON COMM

Members TWTEL1 = TIME WARNER TELECOM WCG01 = WILTEL

COMMUNICATION

You are responsible for contacting any other utilities that are not listed above

including the following tier 2 members not notified by the center:

DNVH20 DENVER WATER DEPT (303)628-6666
DNVPR1 DENVER PARKS & REC. (303)458-4839
DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001
WWMG01 WASTEWATER MGMT DIVISION (303)446-3744



Property Access Checklist

Property Owner: Siden & Alcjandro Prope Home Fax: Cell/P	ORK STARTED ON:// ORK COMPELTED ON://_ orty Renter:
Property Owner: Side & Alcjand Ro Property Owner: Mailing Address: Home Fax: Cell/P Home Phone: (303) 308 - 1387 Addition Fax: W: (303) 297 - 0591 Cell/Pager: Maccess Agreement Signed: // Access Agreement Signed: // Access Agreement Signed: // Topsoil Sampling (if applicable) // Disposal Sampling (if applicable) // Garden Sampling (if applicable) // Utility Clearance Called: // Video/Photos (Before) On: On: O2/22/26/26	rty Renter:
Home Fax: Cell/P Home Phone: (303) 308 - 1387 Addition Access Agreement Addition Access Agreement Access Ac	rty Renter:
Home Fax: Cell/P Home Phone: (303) 308 - 1387 Addition Access Agreement Addition Access Agreement Access Ac	
Alexandro	Phone:
Home Phone: (303) 308 - 1387	
Home Phone: (303) 308-138 Addition Fax: \(\omega: \) (303) 297-0591 Cell/Pager:	
Cell/Pager: Notification Letter Sent:// Access Agreement Signed:/_/ Restoration Agreement Signed:// Topsoil Sampling (if applicable) // Disposal Sampling (if applicable) // Garden Sampling (if applicable) // Utility Clearance Called:/_/ Video/Photos (Before) On:/27_/_6	ional Information:
X Notification Letter Sent:/_/_ X Access Agreement Signed:/_/ X Restoration Agreement Signed:/_/ ☐ Topsoil Sampling (if applicable) /_/_/ ☐ Disposal Sampling (if applicable) /_/_/ ☐ Garden Sampling (if applicable) /_/_/ ☐ Utility Clearance Called:/_/ X Video/Photos (Before) On:	
X Access Agreement Signed:/_/ X Restoration Agreement Signed:/_/ ☐ Topsoil Sampling (if applicable) /_/_/ ☐ Disposal Sampling (if applicable) /_//_ ☐ Garden Sampling (if applicable) /_//_ ☐ Utility Clearance Called:/_/ X Video/Photos (Before) On:	
X Access Agreement Signed:/_/ X Restoration Agreement Signed:/_/ ☐ Topsoil Sampling (if applicable) /_/_/ ☐ Disposal Sampling (if applicable) /_//_ ☐ Garden Sampling (if applicable) /_//_ ☐ Utility Clearance Called:/_/ X Video/Photos (Before) On:	
X Restoration Agreement Signed:// Topsoil Sampling (if applicable) //_ Disposal Sampling (if applicable) //_ Garden Sampling (if applicable) //_ Utility Clearance Called:// X Video/Photos (Before) On:O1/_27/_6	By:
☐ Topsoil Sampling (if applicable) // ☐ Disposal Sampling (if applicable) // ☐ Garden Sampling (if applicable) // ☐ Utility Clearance Called:// ☒ Video/Photos (Before) On:O1/_27/6	By:
□ Disposal Sampling (if applicable) //_ □ Garden Sampling (if applicable) //_ □ Utility Clearance Called:// ☑ Video/Photos (Before) On:	By:
☐ Garden Sampling (if applicable) //_ ☐ Utility Clearance Called:// ☒ Video/Photos (Before) On:/	Ву:
☐ Utility Clearance Called: / / ☑ Video/Photos (Before) On: O1 / 22 /	By:
Video/Photos (Before) On: 01/27/6	By:
	By:
☐ Video/Photos (During) On://_	5 By: M. Redfern
	By:
☐ Video/Photos (After) On://_	Ву:
☐ Video/Photos (30-Day) On://	
Property Completion Agreement Signed://	By:
Final Report Issued://	By:
Air Monitoring (as applicable)	
Community Crew On: / / By:	A STATE OF THE STA
Results:	
Community Cross On / / Pur	
Results:	
Community Crew On:// By:	
Results:	



Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID: 3569	
Property Address: 4726 Sheals	
Owner: algandro Gardea	
Phone: 303) 909-5511 303) 308-1387	

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	
	dog Pears, all misc. items in yard, funiture,
Item:	
7	Dode cana, table
Item:	



NA

item:

Items To Be Removed By Contractor During Remediation And <u>Not Replaced</u> (Use additional sheets as necessary)

Item	
Item	
Item	
Item	
ltem	i terra i tempo de monte en la compansa de la comp L
Item	
	Items To Be Removed By Contractor During Remediation And Replaced
	(Use additional sheets as necessary)
ltem:	(Use additional sheets as necessary)
Item:	(Use additional sheets as necessary) - ∾A
	(Use additional sheets as necessary)
Item:	(Use additional sheets as necessary)
item:	(Use additional sheets as necessary)
Item:	(Use additional sheets as necessary) - NA
Item: Item: Item:	(Use additional sheets as necessary) - NA




Landscape Inventory (Use additional sheets as necessary)

ltem	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	·	Square Feet	
Number of trees > 2 inch trunk diameter			
Number of trees < 2 inch trunk diameter			
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.			Zones: Heads: Control Valves:
Number of and total size of all gardens / flower beds.	# Of Beds:		Ft ² Of Beds:
Attach a sketch of relative sizes and locations.	# Of Gardens:		Ft ² Of Gardens:



Item	Quantity	Unit	Description/Explanation
Agreed upon value of plant materials not to be replaced by contractor. Note this value will be used to issue a plant voucher to the property owner.	Total # Of Beds:	\$	Total Ft ² Of Beds To Be Replaced With Certificate:
Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed. Include a sketch of were each plant will be placed by the contractor.	·	Each	Only Use For Plants That Are Being Saved and Replanted
Agreed upon area of property to be replaced with grass sod. Include a sketch of the area(s) to be replaced with grass sod.		SF	Total Ft ² Of Sod To Be Laid:
Area of City or County property to be landscaped per their requirements. Include a sketch of the area (s)	Total Fr ² :	SF	Sod: Brown Mulch: Red Mulch:
Agreed upon area of property to be replaced with mulch.	Total Ft ² Of Mulch:	SF	Red:



Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock:	SF	Large: Medium: Small (pea gravel): Driveway Gravel:
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover:		

	Additional Comments / Instructions:
·	



	Additional Comment	s / Instructions Continued	
		·	
pre-existing damage	Owner does not want PRI to By checking this box PF uding foundation cracks or	RI is not responsible for a	dation walls and possible any damage done to the
☐1 agree	☐ I do not agree	Tagree	I do not agree
. 111/2	1/ -/-/-		> 0 11 > 21 1
Owner's Signature	<u>Mdea 2/2/2/05</u> Date	Contractor's Signat	ure Date

This spreadsheet performs screening level calculations to estimate the effect of peeling leaded paint on the average concentration of lead in yard soil 4726 High Street

INPUTS	Variable	Units	House
General	Mixing depth in yard	2.54	
	Mixing depth in yard	inches	1
	Soil density	g/cm3	2.5
	RBC in soil	mg/kg	400
	Bkg in clean fill	mg/kg	50
	_	<u> </u>	Small
House-specific	Area of the exposure unit	m2	75.80888
·	Area of the exposure unit	ft2	816
	Concentration of lead in paint	mg/cm2	4
	Area of peeling paint	m2	0.185806
	Area of peeling paint	ft2	2
COMPUTATIONS	,		
	Mass of lead from paint	mg	7.4E+03
	Volume of soil	cm3	1.9E+06
	Mass of soil	kg	4.8E+03
	Incremental concentration	mg/kg	1.5
	Maximum acceptable area of p		42.1
	Maximum acceptable area of p		453.2
DECISION			ок

Peeds to be Filed,
BUT can't File...

Lead Based Paint Qualification Calculations


Property ID	Positive XRF Readings	SF of Peeling Paint	Comments
Property ID 3569	Positive XRF Readings 2047	2	Highest XRF Reading Detected 4
		-	The state of the s
• • • • • • • • • • • • • • • • • • • •			· · · · · · · · · · · · · · · · · · ·
		† · · · · · · · · · · · · · · · · · · ·	
			Majority of house was intact and was not assessed for LBP.
			
	· · · · · · · · · · · · · · · · · · ·	1	
**			· · · · · · · · · · · · · · · · · · ·
	· · · · · · · · · · · · · · · · · · ·		

	······································		
		<u> </u>	

House Total SF of Peeling Paint Garage Total SF of Peeling Paint

2

1 7/21/2006





Daily Quality Control Report VB/I-70

Date: 07-21-06

Lead Based Paint Assessment

Property Location 4726 High 5+

Type and Location of Tests Performed and Results House INTALY OR NEW ADD-ON

2048 0.29 W S.W. pouch Colvar Chipped Peeling Intact Cracked Chipped Peeling	1 ypc a	nu Location of	1 6363 1 611	IVI IIIEU AIIU	1/Courts						
The content of the	Property.	XIII Kaning	PE Lead	Result #374		77.16	ton o Result	Condition	a - Square Pears	Substrine	Color .
Double Calibration Calib						CAliha	Atm)	Intact Cracked			
Suys 1.1 Calibration Intact Cracked Chipped Peeting Intact Cracked Chipped Peeting Intact Cracked Chipped Peeting Intact Cracked Chipped Peeting Intact Cracked		1				paliha	A Tinal	Intact Cracked			
Sold				 							
2048 0.00 W S.W. pouch Flore Dilated Cracked Chipped Peeling Intact Cracked Chipped Peeling		8045	1.1			CALIBRA	+ 700d	Chipped Peeling			
2048 0.29 W S.W. parch Lotter Chipped Peeling 2049 0.00 So South Transite was Chipped Peeling Intact Cracked Chipped Peeling	1	2046		0.00	W	souch	Floor_				
2048 0-29 W S.W. South Colvar Chipped Peeling Intact Cracked Chipped Peeling			4.0		W		1 1.00.7/		1/421	WOOD	white
Dodd Dodd So South Transfer with Chipped Peeling Intact Cracked Intact Cr		1		0,29	W						
Intact Cracked Chipped Peeling		2049		0.00	Sø			Intact Cracked Chipped Peeling		THEADSTE	white
Intact Cracked Chipped Peeling		' '	į	Į į							
Intact Cracked Chipped Peeling			1	 		1 2 2 2 2	1				
Chipped Peeling Intact Cracked Chipped Peeling	L										
Intact Cracked Chipped Peeling	Í	İ									
Chipped Peeling Intact Cracked Chipped Peeling Intact Cracked Chipped Peeling Chipped Peeling	ļ		 								
Intact Cracked Chipped Peeling Intact Cracked Chipped Peeling Chipped Peeling							• • •				
Chipped Peeling Intact Cracked Chipped Peeling		 	 								
Intact Cracked Chipped Peeling			1						1	ł	1
Chipped Peeling				70	\triangleright				† 		
			<u> </u>	ラ ル	`			Chipped Peeling			
								Intact Cracked	-		
Chipped Peeling		<u> </u>	<u></u>				<u></u>				
Intact Cracked											1
Chipped Peeling	ļ									ļ	
Intact Cracked	1								1	1	1
Chipped Peeling		 	 							 	
Intact Cracked Chipped Peeling	1		ļ						,		Į
Intact Cracked		 	 							 	
Chipped Peeling	1	1								Ī	1

I certify that the above report is con equipment, and workmanship are ir

have inspected all work performed this day and have determined that all materials, where noted herein.

Contractor's Quality Control Representative

ngs m 6 rune

TARGET SHEET

EPA REGION VIII SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1035170

	DOC	OWIENT NOWIBER. 1000110
SI	TE NAME:	VASQUEZ BOULEVARD AND 1-70
DO	DCUMENT DATE:	01/26/2006
Dι	ue to one of the fo	DOCUMENT NOT SCANNED lowing reasons:
	PHOTOGRAPHS	
	3-DIMENSIONAL	
	OVERSIZED	,
V	AUDIO/VISUAL	
	PERMANENTLY	BOUND DOCUMENTS
	POOR LEGIBILIT	Υ
	OTHER	
	NOT AVAILABLE	
		MENTS NOT TO BE SCANNED Data Validation, Sampling Data, CBI, Chain of Custody)
DC	OCUMENT DESCR	IPTION:
	3 - DVDs OF PRO	PERTY VIDEO, PROPERTY #3569